Oil Field Environmental Incident Summary

Responsible Party: ENDURO OPERATING, LLC **Well Operator:** ENDURO OPERATING, LLC

Well Name: NDCA CTB

Field Name: MCGREGOR Well File #:

Date Incident:11/5/2015Time Incident:09:00Facility ID Number:202009-01County:WILLIAMSTwp:158Rng:95Sec:16Qtr:NE NW

Location Description:

Submitted By: Scott Hunskor Received By:

Contact Person: Scott Hunskor

777 MAIN STREET

SUITE 800

FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 30 Barrels 30 Barrels 30 barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 11/27/2015 Clean Up Concluded: 11/9/2015

Risk Evaluation:

none

Areal Extent:

South of the dike in a small area

Potential Environmental Impacts:

none

Action Taken or Planned:

Repair pop off from venting. empty cellar. Vac truck to load liquid off ground. wash off ground and pick up with vac truck. Replace old style pop off with an improved one.

Wastes Disposal Location: The waste is being hauled to a holding tank off location. It will then be later disposed of at an approved facility

Agencies Involved:

Updates

Date: 11/6/2015 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater popoff, was not contained according to the report. Further followup needed.

Date: 11/10/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:00 11/10/2015.

Marginal amount of cleanup has been done on location. A brine spill occurred at the same location south of the CTB location earlier this summer. Confirmation sampling will need to be done at the location.

More followup is necessary.

Date: 7/26/2016 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/26/2016 at 12:45, on location. Vegetation growing around entirety of wellpad except south/southwest corner where brine spill occurred (see incident #20150316144105). No further follow-up required for the treater popoff incident at this time.